

PRODUCT TECHNICAL UPDATE NOTICE

Laser 7407 Button Connector Pliers with Flexible Cable

Dear Customer,

As part of our ongoing product improvements we would like to make you aware of a minor potential technical issue with some of the Laser 7407 stock.

Issue:

The plastic holding clip for the inner cable incorrectly orientated on the handle end, resulting in the return spring that is mounted in the working end of the tool being pushed out.

Solution:

Simply remove the plastic clip, turn it around and slide back into position, as shown below.

